



Release Date: March 2015

PRESSURE/TORQUE CONVERSION CHART

<b>PRESSURE IN PSI</b>	<b>FT. LBS.</b>	<b>N-m</b>	<b>3MD</b>
1000	308	418	
1200	367	498	
1400	435	590	
1600	498	675	
1800	565	766	
2000	632	857	
2200	695	942	
2400	760	1030	
2600	828	1123	
2800	892	1209	
3000	960	1302	
3200	1022	1386	
3400	1091	1479	
3600	1156	1567	
3800	1225	1661	
4000	1292	1752	
4200	1359	1843	
4400	1423	1929	
4600	1488	2017	
4800	1551	2103	
5000	1616	2191	
5200	1680	2278	
5400	1744	2365	
5600	1808	2451	
5800	1872	2538	
6000	1935	2624	
6200	1997	2708	
6400	2063	2797	
6600	2127	2884	
6800	2188	2967	
7000	2254	3056	
7200	2318	3143	
7400	2378	3224	
7600	2442	3311	
7800	2504	3395	
8000	2560	3471	
8200	2620	3552	
8400	2683	3638	
8600	2741	3716	
8800	2805	3803	
9000	2860	3878	
9200	2926	3967	
9400	2987	4050	
9600	3045	4128	
9800	3107	4213	
10000	3167	4294	

For Reference Only