




PRESSURE/TORQUE CONVERSION CHART

PRESSURE IN PSI	FT. LBS.	N-m 4HP-HD
1000	409	554
1200	495	671
1400	578	784
1600	675	915
1800	760	1031
2000	837	1135
2200	939	1273
2400	1016	1377
2600	1119	1517
2800	1198	1624
3000	1277	1732
3200	1381	1872
3400	1457	1975
3600	1553	2106
3800	1648	2234
4000	1734	2351
4200	1820	2468
4400	1912	2592
4600	2005	2718
4800	2096	2841
5000	2185	2963
5200	2277	3087
5400	2368	3210
5600	2459	3334
5800	2550	3458
6000	2640	3579
6200	2732	3704
6400	2822	3826
6600	2908	3943
6800	2996	4063
7000	3083	4180
7200	3172	4301
7400	3260	4419
7600	3348	4539
7800	3438	4661
8000	3512	4762
8200	3592	4870
8400	3677	4985
8600	3771	5113
8800	3852	5222
9000	3936	5337
9200	4028	5462
9400	4108	5569
9600	4198	5692
9800	4282	5806
10000	4369	5923



For Reference Only